

4. Plant & Attachments

OTP

OTP No	Supplier Plant ID No	POV (12 Digit) ID No	Туре	Supplier	ALO MLD High Integrity	Planned to lift
1	XEK 2222	99079-1111111	PC138	RPA Plant Hire	No	Yes
2					Yes/No	Yes/No
3					Yes/No	Yes/No
4					Yes/No	Yes/No
5					Yes/No	Yes/No
6					Yes/No	Yes/No

Attachments

Attachment No	Туре	Attachment No	Туре	Attachment No	Туре
K1234	Panel Grab				

Non Rail Mobile Plant

Machine No	Supplier Plant ID No	Туре	Supplier	ALO MLD High Integrity	Planned to lift
1	JCB1234	JZ140	RPA Plant Hire	No	No
2				Yes/No	Yes/No
3				Yes/No	Yes/No
4				Yes/No	Yes/No
5				Yes/No	Yes/No
6				Yes/No	Yes/No

Add rows to above tables as required